# Bell Home Inspections June 19th 2023, 6:50 pm

Inspection performed by: Scott Bell

2087848963

sbellhomeinspections@gmail.com

**General Information** 

BUILDING ADDRESS: Home

CITY: Bonners

STATE / PROVINCE: idaho
POSTAL CODE: 83805

**INSPECTION DESCRIPTION:** SINGLE FAMILY LOG HOME

**SQUARE FOOTAGE**: 2509

Picture:



Has the PRE-INSPECTION AGREEMENT been signed by the client?

Yes

Is the client present for the inspection?

Yes

Is the real estate agent present for the inspection?

No

# **EXTERNAL AMENITIES**

FENCE N/A

Notes:

Animal fence with T post

### **ROOF**

**ROOF TYPE** Gable


Notes:

Metal roof

**ROOF MATERIAL** Metal Standing Seam

Notes:

Some loose screws. Recommend repairing or replacement by qualified roofer.





**ROOF INSTALLATION** 

Satisfactory

Notes:

**CHIMNEY** Inspected


Inspected from latter. Steep pitch.

2 stove pipes observed, boot and pipe appear to be in good condition.

One chimney is missing roof support. Recommend replacement by qualified roofer or chimney contractor.







**FLASHING** Satisfactory

**GUTTERS AND DRAINAGE** N/A

Notes:

No gutters.

MILDEW PRESENT ON ROOF? No

Notes:

### **EXTERIOR**

SIDING MATERIAL Wood

Notes:

Log cabin

**SIDING CONDITION** Inspected

Notes:

Logs are not stained or sealed. Chinking has shrunk. Does not properly seal between logs.


Recommend further evaluation from qualified Log Home repair specialist.

















**EAVES** Inspected

Eaves are not painted or stained.

Recommend further evaluation by qualified painter.









**FASCIA** Satisfactory

**SOFFITS** Satisfactory

Notes:

**TRIM** Satisfactory

Notes:

**EXTERIOR DOORS** Inspected

Notes:

**DECKS** Inspected

Notes:

Some uprights missing from deck. Recommend further evaluation by qualified carpenter for safety.





**STEPS** Poor

Steps are rotting. Recommend further evaluation by qualified carpenter.





# **LANDSCAPE**

**GRADING** Inspected

Notes:

**SURFACE DRAINAGE** Satisfactory

Notes:

# **GARAGE**

**DRIVEWAY** Not Inspected

Notes:

Dirt rock road, in poor condition

# **ATTIC**

**ROOF SHEATHING** Not Inspected

Notes:

Osb sheeting covers framing and insulation. Unable to see roof sheating.





FRAMEWORK Not Inspected

Notes:

Framework covered by OSB Sheeting. Not inspected.

**VENTILATION** Satisfactory

Notes:

Loft attic closet on 2 sides. Adequate venting from soft vents





**INSULATION** Not Inspected Notes:

Vaulted ceiling with Tongue and Groove. No access available.



CHIMNEY AREA Inspected

Notes:

Moisture stains around chimney on sheeting. Currently dry. Recommend monitoring for leaks or further evaluation from chimney contractor.

MILDEW PRESENT IN ATTIC? No

Notes:

**SIGNS OF PESTS IN ATTIC?** No

#### **BATHROOM 1**

**DOORS** Satisfactory

Notes:

**FLOORING** Satisfactory

Notes:

Vinyl floor

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILING** Satisfactory

Notes:

**COUNTERS** Satisfactory

Notes:

**SINKS** Satisfactory

Notes:

**BATHTUB / SHOWER** Satisfactory

Notes:

**TOILET** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

**VENTING** Satisfactory

Notes:

## **BATHROOM 2**

**DOORS** Satisfactory

Notes:

**FLOORING** Satisfactory

Notes:

**WALLS** Satisfactory

Notes:

**WINDOWS** Satisfactory

**CEILING** Satisfactory

Notes:

**COUNTERS** Satisfactory

Notes:

**SINKS** Satisfactory

Notes:

**BATHTUB / SHOWER** Satisfactory

Notes:

**TOILET** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

**VENTING** Satisfactory

Notes:

**BEDROOM 1** 

**DOORS** Satisfactory

Notes:

**FLOORING** Satisfactory

Notes:

Raw plywood floor

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILINGS** Satisfactory

Notes:

**CLOSETS** Satisfactory

Notes:

**OUTLETS** Inspected

Notes:

Broken face plate on one outlet. Recommend replace for safety by licensed electrician.



**LIGHTING** Satisfactory

### **BEDROOM 2**

**DOORS** Satisfactory

Notes:

**FLOORING** Satisfactory

Notes:

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILINGS** Satisfactory

Notes:

**CLOSETS** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

# **BEDROOM 3**

**DOORS** Satisfactory

**FLOORING** Satisfactory

Notes:

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILINGS** Satisfactory

Notes:

**CLOSETS** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

#### **BEDROOM 4**

**FLOORING** Satisfactory

Notes:

Large Recreation room in basement. Concrete floor. Cracks typical for this type of foundation.

**WALLS** Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILINGS** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

# **LIVING AREA 1**

**DOORS** Satisfactory

Notes:



**FLOORING** Satisfactory

Slate tile

**STAIRWAYS** Inspected

Notes:

Railings on stairway and loft have no uprights. Recommend further evaluation by qualified carpenter for safety.



WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory



**CEILING** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Inspected

Notes:

Uncover ceiling box.

Recommend installing cover plate and/or fixture by licensed electrician for safety.



FIREPLACE Not Inspected

Notes:

Over 60 degrees outside.

Stove and pipe appear to be installed correctly.



### **LIVING AREA 2**

**FLOORING** Satisfactory

Notes:

Loft room.

Carpet

STAIRWAYS N/A

Notes:

See prior pics and notes for stairs and railings.

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILING** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**LIGHTING** Satisfactory

Notes:

**KITCHEN** 

**FLOORING** Satisfactory

Notes:

WALLS Satisfactory

**WINDOWS** Satisfactory

Notes:

**CEILING** Satisfactory

Notes:

**COUNTERTOPS** Satisfactory

Notes:

**CABINETS** Satisfactory

Notes:

**PANTRY** Satisfactory

Notes:

SINK / GARBAGE DISPOSAL Satisfactory

Notes:

No garbage disposal

**STOVE / OVEN** Satisfactory

Notes:

**EXHAUST HOOD** Not Inspected

Notes:

No exhaust hood.

**REFRIGERATOR** Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

**DINING ROOM** 

**DOORS** Satisfactory

Notes:

**FLOORING** Satisfactory

Notes:

WALLS Satisfactory

Notes:

**WINDOWS** Satisfactory

Notes:

**CEILING** Satisfactory

Notes:

**OUTLETS** Satisfactory

**LIGHTING** Satisfactory

Notes:

# **LAUNDRY ROOM**

**OUTLETS** Satisfactory

Notes:

GAS SUPPLY Inspected

Notes:

Propane from large propane tank in yard

WATER SUPPLY Satisfactory

Notes:



**DRAINAGE** Satisfactory

Notes:

**CABINETS** Satisfactory

Notes:

# **FOUNDATION**

**FOUNDATION MATERIAL** Poured Concrete

Notes:

Walk out basement.

WALLS Satisfactory

Notes:

**OUTLETS** Satisfactory

Notes:

MILDEW PRESENT AT FOUNDATION? No

Notes:

### **PLUMBING**

WATER SUPPLY PRESSURE Satisfactory

WATER SUPPLY PIPING SIZE Satisfactory

Notes:

MAIN SHUTOFF VALVE Satisfactory

Notes:



SINK / TOILET SHUTOFF VALVES Satisfactory

Notes:

PRESSURE AT FAUCETS Satisfactory

Notes:

SEWER / SEPTIC Not Inspected

Notes:

Septic excluded from inspection.

WATER HEATER Inspected

Notes:

Intsta hot water heater was installed new when current owner purchased the property in 2020.

Pex pipe and propane lines exposed coming through floor. Recommend putting a cover or shield around for safety by owner or qualified handyman.





**VENT SYSTEM** Fair

Water heat vents out through ceiling and roof. Metal heat gard missing. Recommend installing by licensed plumber for safety against fire.



ELECTRICAL
SERVICE DROP / LATERAL Not Inspected

Underground lateral from solar panels. 24v, 3500 watt inverter, with generator back up.

Solar is excluded from inspection.









AMP RATING 200 Amps

Notes:

MAIN DISCONNECT Satisfactory

Notes:



WIRING METHOD Non-Metallic Sheathed Cable

Notes:

**CIRCUIT PANEL** Satisfactory

Notes:

# **HEATING & COOLING**

**ENERGY SOURCE** Wood

Notes:

**VENTING / CHIMNEY** Satisfactory

Notes:

Home is off grid. Primary heat is wood burning stoves. 1 in living room and 1 in the basement.









**HEATING SYSTEM** Electric Heat

Home has electric baseboard and wall heaters. Owner states they are not used because of the solar polar power, but can be use if powered by the generator.

The breakers that are taped off are for heating and electrical systems not being used.


















**HEATING SYSTEM OPERATION** Not Inspected

Not inspected per owners request.

**SMOKE ALARM(S)** Satisfactory

Notes:

CARBON MONOXIDE ALARM(S) Satisfactory

Notes:

**ADDITIONAL DETAILS** 

#### **SUMMARY:**

#### **Roof - Roof Material**

Some loose screws. Recommend repairing or replacement by qualified roofer.

#### **Roof - Chimney**

Inspected from latter. Steep pitch.

2 stove pipes observed, boot and pipe appear to be in good condition.

One chimney is missing roof support. Recommend replacement by qualified roofer or chimney contractor.

#### **Exterior - Siding Condition**

Logs are not stained or sealed. Chinking has shrunk. Does not properly seal between logs.

Recommend further evaluation from qualified Log Home repair specialist.

#### **Exterior - Flashing**

Metal flashing missing.

#### **Exterior - Eaves**

Eaves are not painted or stained.

Recommend further evaluation by qualified painter.

#### **Exterior - Decks**

Some uprights missing from deck. Recommend further evaluation by qualified carpenter for safety.

#### **Exterior - Steps**

Steps are rotting. Recommend further evaluation by qualified carpenter.

#### **Attic - Roof Sheathing**

Osb sheeting covers framing and insulation. Unable to see roof sheating.

Attic - Insulation

Vaulted ceiling with Tongue and Groove. No access available.

#### **Bedroom 1 - Outlets**

Broken face plate on one outlet. Recommend replace for safety by licensed electrician.

#### Living Area 1 - Stairways

Railings on stairway and loft have no uprights. Recommend further evaluation by qualified carpenter for safety.

#### **Living Area 1 - Ceiling Fans**

Uncover ceiling box.

Recommend installing cover plate and/or fixture by licensed electrician for safety.

#### Living Area 1 - Fireplace

Over 60 degrees outside.

Stove and pipe appear to be installed correctly.

#### **Living Area 2 - Flooring**

Loft room.

**Carpet** 

#### **Plumbing - Water Heater**

Intsta hot water heater was installed new when current owner purchased the property in 2020.

Pex pipe and propane lines exposed coming through floor. Recommend putting a cover or shield around for safety by owner or qualified handyman.

### **Plumbing - Vent System**

Water heat vents out through ceiling and roof. Metal heat gard missing. Recommend installing by licensed plumber for safety against fire.

### **Electrical - Service Drop / Lateral**

Underground lateral from solar panels.

24v, 3500 watt inverter, with generator back up.

Solar is excluded from inspection.

### **Heating & Cooling - Venting / Chimney**

Home is off grid. Primary heat is wood burning stoves. 1 in living room and 1 in the basement.

### **Heating & Cooling - Heating System**

Home has electric baseboard and wall heaters. Owner states they are not used because of the solar polar power, but can be use if powered by the generator.

The breakers that are taped off are for heating and electrical systems not being used.